

# Report of Inspection/Test



FIRE SPRINKLER INSPECTIONS

Annual Riser

November 19, 2009

## Property

Test  
123 Acme  
Ann Arbor, MI 48108

## Owner/Agent

Test  
123 Acme  
Ann Arbor, MI 48108

815 Airport Boulevard  
Ann Arbor, Michigan 48108

Office: 734-761-8088  
Fax: 734-761-8103

Conducted by:  
Inspection Ref:

Joe Smoe  
(734)761-8088

Joe Smoe  
(734)761-8088

## B. Alarms

- |     |  |
|-----|--|
| Yes | B1. All accessible tamper switches operate properly?             |
| Yes | B2. Inspectors test connection accessible and in good condition? |
| NA  | B3. Mechanical water flow devices operate properly?              |
| Yes | B4. Electrical water flow devices operate properly?              |
| Yes | B5. Did the audible/visual signal operate?                       |
| Yes | B6. Alarm system monitored by a central station?                 |
| Yes | B7. Signal received by central station?                          |

## C. Wet System

- |     |  |
|-----|--|
| NA  | C1. Hydraulic nameplate securely attached and legible?                 |
| Yes | C2. Gauges in good condition and showing normal water supply pressure? |
| Yes | C3. Does there appear to be adequate heat in the riser area?           |

## D. Main Drain Flow Test

- |     |  |
|-----|--|
| Yes | D1. Main drain valve accessible and in good condition?                           |
| Yes | D2. Does the main drain terminate in an acceptable place for full flow of water? |
| 76  | D3. Record static pressure before test   |
| 67  | D4. Record residual pressure   |
| 70  | D5. Record static pressure after test  |
| Yes | D6. Test results appear acceptable?  |

## F. Fire Department Connection

- |     |   |
|-----|---|
| Yes | F1. Check valve appears to be leak free?  |
| Yes | F2. Automatic ball drip in place and operating properly?                          |
| Yes | F3. Connection is visible and accessible?   |
| Yes | F4. Couplings free of damage and rotate smoothly?                                 |
| Yes | F5. Are all caps in place and does the connection appear to be in good condition? |

## G. Control Valves

- |     |   |
|-----|---|
| Yes | G1. All control valves accessible?                                      |
| Yes | G2. All accessible control valves in correct (open or closed) position? |
| Yes | G3. All accessible control valves sealed, locked or supervised?         |
| Yes | G4. All accessible control valves appear to be in good condition?       |

## M. Sprinklers

- |     |  |
|-----|--|
| Yes | M1. Properly stocked spare head cabinet available? |
|-----|--|

## Z. Inspection Notes

Notes:

**This inspection was a "riser" inspection. Sprinkler heads and sprinkler coverage were not inspected. Inspection is limited to the questions and answers within this report only.**

**This report and recommendations within it are only intended to assist the customer in reducing the possibility of loss or damage to the property by indicating defects/impairments to the system/equipment at that location and at the time of inspection. The final responsibility for the condition, maintenance and operation of the fire sprinkler system lies solely with the customer.**

## Report of Inspection/Test

Annual Riser  
November 19, 2009

Property: Test  
Owner: Test

 **Arbor Inspection  
Services, LLC**  
FIRE SPRINKLER INSPECTIONS

### Deficiency Summary

These items were deficient and do not meet the requirements of the applicable code at the time of the inspection. Items marked *Recommendation* are not required by the applicable code but are opportunities to improve the Life Safety of the property.

### Z. Inspection Notes

#### Notes:

This inspection was a "riser" inspection. Sprinkler heads and sprinkler coverage were not inspected. Inspection is limited to the questions and answers within this report only.

This report and recommendations within it are only intended to assist the customer in reducing the possibility of loss or damage to the property by indicating defects/impairments to the system/equipment at that location and at the time of inspection. The final responsibility for the condition, maintenance and operation of the fire sprinkler system lies solely with the customer.